
Customer Controlled Routing

CCR messages

CCR0001	{link number} {hours} {minutes} {seconds} {length of output queue} {length of system input queue} {length of call process input queue}
CCR0002	Link congestion or slow response time detected on the CCR link. Cleaning up the link. Link cleanup completed.
CCR0003	The CDN is being switched to default mode because the CDN is unknown to the CCR application, or there is no call script defined. The operator is required to fix the problem and reset the CDN back to control mode if so desired.